

# TECHNICAL SERVICE BULLETIN



NO.

3 G 5

June, 1970

SUBJECT:

Boring Engines Under Warranty

MODELS:

All Models

In the future, pistons will not be supplied in .010" oversize. Therefore, it will not be possible to bore engines to this size as specified by Section 15 of the Warranty Policy and Procedures Manual.

It will be permissible to bore engines to .020" after the first 4,000 miles.