

TECHNICAL SERVICE BULLETIN

NO. 71 A 14



August, 1971

SUBJECT:

Valve Rocker Gear Lubrication

MODELS:

MGB

From the undermentioned Engine Nos., the drilling through the rocker arm and bush to the tappet adjusting screw and the radial groove and drilling within the adjusting screw, have been deleted, thus eliminating pressure feed lubrication to this point.

18GKWEH 9986, 18GKRWEH 9492

Summary of Parts Changes

<u>Old Part No.</u>	<u>Description</u>	<u>Qty.</u>	<u>New Part No.</u>
12H 2037	Rocker - valve	8	12H 3377
1G 2295	Bush	8	12H 2197
48G 207	Screw - tappet adjusting	8	12H 3376