



TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

January 30, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Transmission Case Oil Drain
Plug Washer

Mini Range
1100 Range

To maintain a positive seal without undue tightening - which could lead to stripping of the plug threads - it is recommended that replacement of the drain plug washer, Part No. 22A 134, should be carried out at alternate oil and filter element changes.

The torque spanner reading for the above plug is 40 to 50 lb. ft. (5.5 to 6.9 kg.m).