

Confidential

# TECHNICAL SERVICE BULLETIN

NO. 2 F 33



DATE: 12/1/69

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

STEERING WHEEL CENTER MOTIF  
'POPPING OUT'

MODELS:

AUSTIN AMERICA

This complaint is usually caused by fracture of the retainer clips and not by errors in sizing of the steering wheel center.

Current stocks of motifs have retainer clips of reduced thickness to allow improved flexibility. These may be recognized by an additional (fourth) adhesive fixing as shown at 'A' in the illustration. The motif part number remains unchanged.

