

Confidential

TECHNICAL SERVICE BULLETIN

NO.

2 G 38

BRITISH



LEYLAND

AUSTIN MG

DIVISION

DATE: 8/20/69

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Shop Manual

MODELS:

MGC

It has come to our attention that in the MGC Shop Manual Section 08.C illustrates and instructs us to install the one way clutch facing in the wrong direction. The correct installation is with the lip side out. This should be corrected immediately. *done*