

Confidential

# TECHNICAL SERVICE BULLETIN

3 A 6

NO.



DATE: May, 1970

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Loose Manifolds

MODELS:

Series A Engines

This problem may be cured by substituting special steel nuts, part number AHH 8382, for the original brass nuts.