

TECHNICAL SERVICE BULLETIN

NO.

3 F 1

BRITISH



LEYLAND

AUSTIN MG
 DIVISION

1/15/70

DATE: _____

BRITISH LEYLAND MOTORS INC.

600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MODELS:

Steering Wheel Nut Tightening

All Models

It is important that steering wheel retaining nuts are never over-tightened and the following torque figures must be strictly adhered to:

Austin America

32 - 37 lb.ft (4.5 - 5.0 kg.m)

 Sprite)
 Midget)
 MGB)

plastic rimmed wheel

40 lb.ft. (5.5 kg.m)

 Sprite)
 Midget)
 MGB)

leather rimmed wheel

28 lb.ft. (3.9 kg.m)

MGC

40 lb.ft. (5.5 kg.m)