

TECHNICAL SERVICE BULLETIN



NO.

3 G 8

August, 1970

SUBJECT:

Passport To Service

MODELS:

All Models

A redesigned Passport To Service Booklet has been introduced and should be placed in all new 1970 vehicles prior to delivery to a customer.

This new Booklet can readily be identified by the revised service recommendations and the built-in identification plate holder which is an integral part of the back inside cover.

It remains vitaly important that the registration card be fully completed and mailed to your Distributor as soon as a sale is finalized.