



TECHNICAL SERVICE BULLETIN

British Motor Holdings (U.S.A.) Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

February 29, 1968

TO ALL DISTRIBUTORS AND DEALERS

Re: 'O' Ring Seals 22A 828

1100 Automatics

Your attention is drawn to the necessity of ensuring that the above seals (3 off) are correctly situated in the grooves of the reverse output gear shaft and not damaged or displaced during fitment of the top and reverse clutch.