

# TECHNICAL SERVICE BULLETIN

NO. 2 D 35



DATE: February 1, 1969

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

**SUBJECT:**

OIL FILTER ELEMENT REPLACEMENT

**MODELS:**

AUSTIN AMERICA )  
AUSTIN 1100 ) Automatics

It is now considered unnecessary to replace the oil filter element at 3000 mile or 3 monthly intervals, "A" service.

Instead, the element should be renewed every 6,000 miles or 6 months, "C" service.

You will note the latest edition of the MG/AUSTIN Passport to Service (WAR. NO. 24/2) does not make any reference to an element change at the "A" service.

This recommendation obviously applies to vehicles already in service, but Dealers may wish to sell more frequent element changes based on the vehicle operating conditions.

IT IS OF PARAMOUNT IMPORTANCE THAT ENGINE OIL ADDITIVES SHOULD NOT BE USED UNDER ANY CIRCUMSTANCES. FLUSHING OILS SHOULD NOT BE USED AS A CONSIDERABLE AMOUNT WOULD REMAIN IN THE TORQUE CONVERTER AFTER DRAINING.