



TECHNICAL SERVICE BULLETIN

British Motor Holdings (U.S.A.) Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

March 1, 1968

TO ALL DISTRIBUTORS AND DEALERS

Re. Passport To Service

A revised Passport To Service (sample enclosed) has been issued for use with the 1968 models.

This revised printing covers the servicing of the emission unit and certain changes in the A, B and C Maintenance Services. We strongly urge you to ensure that both your sales and service personnel are familiar with these changes with particular attention being paid to the following....

<u>PAGE</u>	<u>ITEM OR SUBJECT</u>
8	10 - Owner's Responsibilities
9	Identification Plate
1,000 Mile Service	Oil Change On Rear Axle Deleted Service and Test Of Emission Unit
13	Air Pollution
14	Safety Features
16	Oil Filter Change Deleted
17	Emission Unit Check
18	Oscilloscope Tune Up Replace Oil Filler Cap Emission Unit Check
25	New Accessories