



TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

March 14, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Passport To Service

A revised Passport To Service (sample enclosed) will shortly be issued to replace the one presently in service. This new issue is NOT to be used until your current stocks are depleted. We strongly urge you to ensure that all your staff are familiar with the contents of the revised book so that they in turn may intelligently review the book with new owners.

Special attention should be paid to the following:

A. Vehicle Registration Card

The registration card is now in duplicate and must be returned to your distributor intact. The information must be complete and typed. It is imperative that it be mailed within 24 hours of the date of delivery.

The distributor address will already be stamped on the card.

B. Maintenance Service

The items on the services have been modified and a new method of recording these services has been devised. It is essential that this record be maintained.

Please note that the 12000 mile service now incorporates an engine tune-up.

P.T.O.

-2-

C. Accessories

The last section of the Passport To Service book has been devoted to accessories and it is to your advantage to have available information and stock of the items listed.

We look forward to receiving your usual fine cooperation.