

# TECHNICAL SERVICE BULLETIN

NO. 71 A 10



May, 1971

SUBJECT:

Choke Setting

MODELS:

Austin America

1971 Model Austin Americas are being received with a black plastic device fitted to the choke control on the fascia panel. This device is fitted for shipping and dock side handling purposes only and should definitely be removed at the pre-delivery inspection.

We would wish to advise that on operation of the choke, to a position where the carburetor jet has not commenced to drop, the fast idle speed should be between 1000 and 1100 rpm.