

TECHNICAL SERVICE BULLETIN

NO. 72 A 1



March, 1972

SUBJECT: Tappets and Push Rods

MODELS: MGB and MGB/GT 18 V Engines

There is a change of specification and part numbers of the tappets and push rods used in MGB and MGB/GT engines for 1972 models.

Would all Service Managers note the following and advise your Parts Managers MGB, PCMI Fiche #AKD 5203, dated January, 1972. Row 07, Column 55, Items 39 and 40 should read as follows:-

<u>Part Number</u>	<u>Description</u>	<u>Application</u>
1H 822	Tappet)	18G Engines Only
12H 1306	Push Rod)	
2A 13	Tappet)	18V Engines (1E 1972 Models On)
12H 3357	Push Rod)	

NOTE: The installed combined length of the tappet and push rod is the same for each group of engines, but individual components are not interchangeable.

DJH