

TECHNICAL SERVICE BULLETIN

NO. 75-G-3



Austin MG

JULY 1975

SUBJECT:

WARRANTY ENGINE REPLACEMENT FOR
MAJOR FAILURE - 1975 MG MIDGET

MODELS:

MG MIDGET

Due to a temporary shortage of short block assemblies, we have arranged for a supply of specially priced complete engine units to be available under part #UKC 5172. Because of the special conditions involved, it is most important that the use of these engine units is restricted to VOR warranty situations.

These engine units (UKC 5172) are complete with carburetor, alternator, belts and clutch, therefore, replacement in a vehicle is accomplished under a shop time allowance of six hours to cover the removal and replacement as a complete assembly. It is essential that when fitting UKC 5172, the displaced unit with the same auxiliary equipment is returned to your Zone/Distributor with your claim.

Claims will be filed in the normal manner using part UKC 5172 and indicating the labor as a shop time of six hours. All other details on the form will be filled out as per normal procedures.

Commensurate with the discount structure on engine units, a parts handling allowance of 17½% will be paid on these warranty claims.

WHG