NO. 2 F 30

DATE: 4/3/69

BRITISH LEYLAND MOTORS INC. 600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MODELS:

RECALL CAMPAIGN-TIRE MARKINGS

MG MIDGET
MGB (Wire Wheels)
MGB/GT

A number of Dunlop and Goodyear tires on which the required words "TUBED TYPE" have been inadvertently omitted from the side walls have been released on MG cars fitted with wire wheels.

The recall campaign is necessary to bring these tires into conformity with the Motor Vehicle Safety Standard #109 by applying the correct identification. The tires in question are perfectly standard in every safety and performance aspect and it is only to correct the omission of the markings that this campaign is necessary.

In accordance with our obligation under Public Law 89-563 we are notifying all Distributors, Dealers and owners of record by this Bulletin and the accompanying draft owner letter. The letter to owners requests them to come to Dealerships so that the self-vulcanizing imprints may be applied to both side walls of all five tires on each vehicle.

Under separate cover you will be receiving an ample supply of these imprints which can be readily attached to the side walls of the tires. All that is necessary is for the area of the side wall to be cleaned with a gasoline damped cloth and then apply the imprint after peeling off its backing.

A sample campaign claim showing simplified submission method to follow under separate cover.

Distributor Claim BRITISH LEYLAND MOTORS INC. WARRANTY CLAIM 1. Dealer Claim No. 2. Date Work Completed 3. Mileage 4. R.O. No. 00000 /69 Fault A Material Labor Dist/Deal Code No. Period 7. Serial No. Code 6. Engine No. Fault B Material Labor 8. Owners Name USE YOUR TIRE MARKING CAMPAIGN 9. Address 5. In Warranty 5. Policy Adj. 5. Camp'n Chg. 10. City & IMPRINTER State SEE LIST BELOW 11. Date of Delivery Use imprinter only 5. Parts Warr'ty 5. Proprietary 5. Reconditioned 11A SELLING DEALER YES □ NO Use Imprinter or type 12. COMM. NO. 13. DESCRIPTION OF PART 14. QTY. 15. PART NO. 16. INVOICE NO. 17. DLR. COST DIST. COST DISTRIBUTOR USE THIS CLAIM IS: GAN4U/58918 GAN4U/63410 Accepted GAN4U/60473 GAN4U/63527 GAN4U/60493 Adjusted GAN4U/64580 See Reason No. GAN4U/60533 GAN4U/66460 GAN4U/60537 Queried. GAN4U/66696 See Reason No. GAN4U/60538 Rejected . GAN4U/60734 See Reason No. AN4U/60806 For Reason No. Refer GAN4U/61278 to Warranty Policy and GAN4U/61292 Procedure Manual. GAN4U/62081 GAN4U/62217 FACTORY USE GAN4U/63032 GAN4U/63066 THIS CLAIM IS: GAN4U/63067 Accepted Adjusted See Reason No. 19. MATERIAL See Reason No. 18. IMPORTANT Rejected 20. SUBLET See Reason No. 21. LABOR For Reason No. Refer \$30 00 FOR FACTORY/DISTRIBUTOR AUTHORIZATION SIGNATURE PRODUCT REPORT NUMBER-CORRESPONDENCE REFERENCE to Warranty Policy and 22. TOTAL Procedure Manual. 23. DESCRIPTION OF FAULT 24. OP.NO. GIVE ALL DETAILS OF WORK COMPLETED. STATE FULLY REASONS FOR REPLACING PARTS. DO NOT USE THE WORD DEFECTIVE. IMPORTANT 1. Total time allowed 0.25 hrs. # of cars x operation time x warranty per car. rate = total \$ labor 2. Complete upper portion of Claim (Boxes 1-12) as shown. Ex. $-20 \times 0.25 \times $6.00 = 30.00 3. List modified vehicle serial prefixes and numbers in numerical sequence as shown. DO NOT MIX MODELS IN ONE CLAIM -- i.e. LIST MGB's ONLY, MIDGETS ONLY, ETC. **FACTORY/DISTRIBUTOR INSPECTION REPORT** 4. Complete Box 23 as per example. 5. Insert total labor figure in Box 21. 6. Sign Claim and submit in the normal manner.